

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:Wallingford, Jonni B. <wallingfordjb@cdmsmith.com>)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:Sheldrake, Sean <sheldrake.sean@epa.gov>)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen, Davis <Zhen.Davis@epa.gov>)
CC: younghs@cdmsmith.com
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott Coffey <coffeyse@cdmsmith.com>)
Date: 7/30/2018 3:21:24 PM
Subject: Subsurface Sediment Coring
Attachments: [Snapchat-441214242.jpg](#)
[Snapchat-668160462.jpg](#)

Attached are photos of SC-S062 (RM 4.6 W), attempt #3. The sediment sample is silt with no observed odors or NAPL present. The core yielded an 87.2% recovery. The second photo shows the core after water has been decanted and cut down to be iced.

Jonni

(b) (6)

Get Outlook for Android<<https://aka.ms/ghei36>>